


















 30	31 061 3 x	 75	35 073 2 x	 38 240 5 x
 15°	31 981 4 x		35 087 1 x	 143 234 3 x
	31 982 3 x	 4	36 323 2 x	 151 715 1 x
	32 064 4 x		36 920 2 x	 155 901 1 x
	32 879 1 x		36 922 2 x	 159 783 1 x
	32 881 4 x		36 973 2 x	 163 200 1 x
	35 049 9 x		37 237 3 x	Erfinder Flexprofil 143 234 und Entwickler 90° Kurve 151 715 Design und Konzeption Andreas Lehrberger

Sicherheitshinweise Safety Information Consignes de sécurité

Veiligheidsrichtlijnen Indicaciones de seguridad Observações sobre segurança

Informazioni per la sicurezza Указания по технике безопасности 安全指南

- Alle Einzelteile, insbesondere bewegliche Teile sind falls notwendig zu warten und zu reinigen.
- All components, especially moving parts, should be maintained and cleaned as necessary.
- Toutes les pièces détachées et en particulier les pièces mobiles, sont, si nécessaire, à entretenir et à nettoyer.
- Alle onderdelen, vooral de bewegende delen, kunnen, indien noodzakelijk, onderhouden en gereinigd worden.

- Es necesario limpiar y mantener en buen estado todas las diferentes piezas - especialmente las piezas móviles.
- Caso necessário, todas as peças individuais, especialmente peças móveis, tem que ser submetidas à manutenção e ser limpidas.
- Se necessario, tutti i singoli componenti, soprattutto le parti mobili, si devono eventualmente sottoporre a manutenzione e pulizia.
- Все детали, особенно подвижные, требуют ухода и чистки.
- 必要时应保养和清洁所有零件，尤指运动部件。